



060001

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Report Date: September 11, 2006

Supervisor

Mine Name: Black Magic Operator Name: Gary Hansen Permit number: S0190062
Inspection Date: 09/05/2006

Inspector(s): Dan Smith **Other Participants:** None

Mine Status: ACT

Weather: No adverse conditions

affecting site visit.

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material			:
5. Roads (maintenance, surfacing, dust control, safety)			
6. Concurrent Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Water Impoundments			
9. Soils			
10. Revegetation			
11. Air Quality			
12. Other			

Purpose of Inspection:

The first inspection of this permit to document conditions at site.

Directions to Site:

Easy access to site from Westwater exit on I-70. See map.

Inspection Summary:

No signs of disturbance. Existing two track road in area.

Conclusions and Recommendations:

Recommend that the primary inspector review this mine permit.

Inspector's Signature

Date: September 11, 2006

ds

cc: Operator

Attachment: Map & Photos





